PRINTED: 10/27/2015 FORM APPPROVED

Division of H	ealth Service Regulation			,							
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA				(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY					
AND PLAN OF CORRECTION IDENTIFICATION NUMBER:				A, BUILDING 01			COMPLETED				
FCL017052				B. WING:		R 09/24/2015					
NAME OF PRO	VIDER OR SUPPLIER				TE, ZIP CODE						
6245 BURTON CHAPEL ROAD HUMPHREY FAMILY CARE HOME MEBANE, NC 27302											
(X4) ID	Miles of the particular state our population of			ID.	PROVIDER'S PLAN OF CORRECTION		(X5)				
PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFIX TAG		EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETE DATE				
	REGULATORY OR LSC IDENTIFYING INFORMATION				DEFICIENCY)						
(C090)	Initial Comments		{C000}								
	Barrest Datis Yes	Class House									
	Report by Robin Fay and	з Свепп норрш									
	DHSR Construction Sect	ion conducted a Biennial									
	Follow-up Survey on Sep										
	10:00 AM to 10:30 AM at the above referenced facility.										
	Not all of the previous cited deficiencies										
1	were corrected. Therefore, further action is										
	required.										
	The remaining deficiencies are as follows:										
	The femaling deficiences are as follows.										
{C 137}	Bathroom-Mechanical Ventilation		{C	37)							
	SECTION .0300- THE BUILDING										
	10A NCAC 13G .0309 BATHROOM										
l	(g) The bathroom shall be lighted to provide 30										
1	Foot candles of light at floor level and have										
]	mechanical ventilation at the rate of two cubic										
	feet per minute for each square foot of floor area.										
	These vents shall be vented directly to the										
	outdoors.										
	This Rule is not met as evidence by:										
	Based on observation, the mechanical										
	exhaust was not maintained operating.										
	The floor is the fact										
	Findings include: The exhaust fan in the back middle bathroom is										
	not working.										
	no working.		}								
	9/24/2015 - RF/GH: At	the time of the follow-up			Administrator purchased a new ventilation fan	and	11/2/15				
	Survey the exhaust fan in the back middle				installed it on November 2, 2015		11/2/13				
	bathroom was not opera										
		ation to this office that the									
	work has been complete				10-						
	photograph or work ord	er.			<i>90</i>						
					1 5						
:					(37						
					l						
Division of Heal	th Service Regulation		-		4	-					

PRINTED: 10/27/2015 FORM APPPROVED

Division of Health Service Regulation (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCES (XI) PROVIDER/SUPPLIER/CLIA COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 AND PLAN OF CORRECTION B. WING: 09/24/2015 FCL017052 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 6245 BURTON CHAPEL ROAD HUMPFIREY FAMILY CARE HOME MEBANE, NC 27302 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES PREFIX EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX TAG DATE CROSS-REFURENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY {C174} (C174) Continued From page 1 {C174} (C174) Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, Mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition, (i) This Rule shall apply to new and existing family care homes. This rule is not met as evidence by: 3. b) The ramp to the bathroom is not protected by handrail the entire length. Install end bracket to secure handrail. Provide documentation to this office that work has been completed with an invoice, photograph or work order Handrail bracket installed to secure handrail 11/2/15 9/24/2015 - RF/GH: Handrail along the ramp to the bathroom is missing an end bracket. Install another bracket to secure handrail. Provide documentation to this office that work has been completed with an invoice, photograph or work order. Based on observation, the electrical components were not maintained operable. Finding include: There are three emergency lights in the corridor with dead batteries 9/24/2015 - RF/GH: At the time of the follow-up 11/2/15 Administrator purchased and replaced survey the corridor emergency lights were not batteries in the emergency lights in corridor amnually operable. Replace batteries. Provide documentation to this office that the work has been completed with an invoice, photograph or work order.

Division of Health Service Regulation

PRINTED: 10/27/2015 FORM APPPROVED

If continuation sheet 3 of 3

STATEMENT OF DEFICIENCIES		(X1) PROVIDER/SUPPLIER/CLIA		TIPLE CONSTRUCTION	(X3) DATE SURVEY					
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	A. BUILDING 01		COMPLETED R					
		FCL017052 B. WING:			09/24/2015					
1			RESS, CITY, STATE, ZIP CODE							
HUMPHREY FAMILY CARE HOME MEBANE, NC 27302										
(X4) ID		TEMENT OF DEFICIENCIES	ID PREFIX	PROVIDER'S PLAN OF CORRECTION EACH CORRECTIVE ACTION SHOULD BE	(X5) COMPLETE					
PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION		TAG	CROSS-REFERENCED TO THE APPROPRIATE	DATE					
				DEFICIENCY)						
i										
					1					
					i					
ì			:							
:										
,										
;										
1										
Division of Health Service Regulation										
STATE FORM			CD	OIP11	If continuation sheet 3 of					